Accessibility Audit and Plan 2021

Area	Provision in place	Need
Car Park and Footpath	There are two disabled parking bays in	
	the car park, one at each end and	
	adjacent to low level kerb. There is also	
	a bay next to the bins between the two	
	schools.	
	The footpath from the main entrance	
	leads to a crossing through the car park	
	giving access to the school.	
	The infant path has been resurfaced.	
	There is a one way system in operation	
	at peak times to minimise crowding.	
Doors and door controls	The front doors and doors to the office	
	is fully compliant for disabled access.	
	The rear doors are compliant width.	
Signage	The school office is signposted from the	
31811450	pathway.	
Finishes and decorations	The main hall floors are finished with a	
	non-glare finish.	
Steps	All steps have yellow edging and	Ensure step edges are maintained.
	handrails.	
Disabled toilets	Disabled toilets are available in all	
Disabled tollets	buildings.	
Communications, alarms and	Alarms installed in disabled toilets.	Pull cord alarms to be tested.
security systems	Alainis installed in disabled tollets.	Website which is DDA compliant.
Ramps, lifts and ramp systems	The main entrances are approached by	Website Willer is DDA compliant.
Ramps, mits and ramp systems	ramps.	
	There is a lift to the upper level in the	
	KS2 building to ensure step free access	
	throughout the school from the front	
	entrance.	
Handrails and hardware	All handrails are warm touch. External	Consider whether all hand rails
Transfer and transfer a	handrails are dual height.	need dual height.
Lighting and acoustics	Emergency lighting in place.	need dad neight
	Staff wear portable induction hearing	
	loop in assembly for children with a	
	hearing impairment.	
Furniture and equipment	Suitable furniture provided for	
	individual children e.g. chair with arms,	
	screens for work stations.	
	Seats in waiting area have arms for ease	
	of use and are in contrasting colour for	
	visibility.	
Emergency access routes	Emergency evacuation procedures for	Ensure personal evacuation plans
	fire include reference to evacuation of	are updated as necessary.
	children with 1:1 support.	
Toileting and changing facilities	Four toilets for disabled users are	
	available. There is a changing area/care	

suite including shower in the infant school.	

Curriculum Access

Area	Provision in place	Need
Information for teachers on	Planning meetings	
differentiating the curriculum	Pupil Progress meetings	
	Provision maps	
All out-of-school activities are	Staff visits prior to event	
planned to ensure the participation	Visual timetables	
of the whole range of pupils	Risk assessments	
	Extra adults	
Classrooms are optimally organised	Classes are organised to be enabling	Regular audit of resources.
to promote the participation and	for all pupils to access resources and	
independence of all pupils	activities independently or with 1:1	
	support as necessary.	
Training for Awareness Raising of	Regular staff training to ensure all	SLT to review needs of pupils and
Disability Issues	staff have necessary resources and	staff needs.
	knowledge to support pupils e.g.	New staff to have induction.
	ASD and Downs Syndrome.	Ongoing.

Written Information

Area	Provision in place	Need
Newsletters and website	Newsletters are emailed to all	Update website to be fully
information	families and are published on the	accessible.
	school website.	
Signage	The school offices is signposted	Ensure signs are clear of dirt and
	from the pathway.	clearly visible.
		Ongoing.
Policies	Behaviour Policy	Review and update as necessary.
	Anti-Bullying Policy	
	Teaching and Learning Policy	Ongoing.